
Unresolved Squawks

Townsend Aviation

N5X5X5

LR31

Page 1 of 1

May 16, 2006

Squawk #	Reported	Description of Problem	MEL	W/C Status
1023 -1	07/15/2004 Hrs: 3,753	Slight fluctuation of L/H oil PSI	MEL Cat: - Due Date: Due Hrs:	Pending
